From:	Ronald L. Earp, Ph.D.
To:	"Jeff Giordano"
Subject:	RE: Table
Date:	Thursday, February 27, 2014 1:21:00 PM

Buddy
Crankshaft Service in Charlotte
704-377-4933

They say they can weld up the keyway, cut it all back down, and recut a new one. But not for cast iron. Can recut the new one by radial degree measurement, so they could indeed move it X degrees.

From: Jeff Giordano [mailto:jeffgio@nc.rr.com]
Sent: Thursday, February 27, 2014 12:54 PM
To: Ronald L. Earp, Ph.D.
Subject: Re: Table

innovative

we should reconsider cutting a new keyway in the crank?

On 2/27/2014 10:16 AM, Ronald L. Earp, Ph.D. wrote:

> http://www.youtube.com/watch?feature=player_embedded&v=_OnF6_V28DM
>
> Interesting.